EXHIBIT K

ч		•			
Inspection Detail					Mar 05,2009 2:18 pm
Site Type Facility	inspection Location				
DEC ID 9146400113	Facility TONAWANDA COKE CORP			i	
Location 3875 RIVER RD TO	ONAWANDA, NY 14150				
Scheduled Date Compliance Status: In Compliance					
Achieved Date 09/09/200	8 Time 2:00 PM		Complete		
inspector(s)	F	rimary			
	SITZMAN*LARRY	Ø			
Inspection Reason(s)	Prev Inspection	AIRS			
Follow Up Inspection	08/23/2007 9:00 AM	348			
Comment			_		
Inspected flare and records of inspection. Battery emergen design but no fuel is hooked	cy flare has a pilot light as	part of the	. •		
Issued Permits	Ren Type Effective		Overall		
9-1464-00113/00031	0 ATV 04/30/2002				

Defendants' Exhibit W

D_W-001

Inspected flare and records as a follow up to the annual inspection. Battery emergency flare has a pilot light as part of the design but no fuel is hooked up to the flare. They are evaluating how to get the flare in compliance with the MACT requirements. Inspected records for annual coke production. The facility provided records for the last 2 years which show that the facility produced just over 75 percent foundry coke with the remainder being furnace coke. Also inspected battery pushing reports for the last 2 weeks of July and the first week of August. I inspected these records as part of an investigation into odor complaints received on July 31. Nothing out of the ordinary was found in the records.